

5.4 PHOTOGRAPH LOG



ORIGINAL  
(Red)

Photo 1 -  
Toluene spill area looking southwest.



Photo 2 -  
Toluene spill area looking north.

5.4 PHOTOGRAPH LOG



ORIGINAL  
(Red)

Photo 1 -  
Toluene spill area looking southwest.



Photo 2 -  
Toluene spill area looking north.



— Photo 3 —  
 — Toluene spill area and limestone gravel —  
 — surface. —



— Photo 4 —  
 — Toluene spill area and monitoring well. —



BASF Wyandotte

F3-8412-17

WV-121

R1P4

Photo No 3

Toluene spill area, Limestone gravel surface

2-4-85

Randall Dickinson

Randall Dickinson

Photo 3 -  
Toluene spill area, limestone gravel  
surface.

BASF Wyandotte

F3-8412-17

WV-121

R1P1

Photo No 4

Toluene Spill area, Monitoring well

2-4-85

Randall Dickinson

Randall Dickinson

Photo 4 -  
Toluene spill area and monitoring well.



— Photo 5 - 31st Street Landfill. Floodwall —  
 — side of landfill showing surface drainage —  
 — ditch, looking south. —



— Photo 6 - 31st Street Landfill —  
 — Crest of landfill, looking south. —  
 — —

BASE Wyandotte

F3-8412-17

WV-121

R2 P2

Photo #

5

2-4-85

2-4-85

31<sup>st</sup> Street Landfill

East wall side of landfill showing surface  
drainage ditch. Looking south

2-4-85

Randall Dickinson

Randall Dickinson

Photo 5 - 31st Street Landfill. East wall  
side of landfill showing surface drainage  
ditch. Looking south.

BASE Wyandotte

F3-8412-17

WV-121

R2 P3

Photo #

6

2-4-85

2-4-85

31<sup>st</sup> Street Landfill

Crest of landfill Looking south

2-4-85

Randall Dickinson

Randall Dickinson

Photo 6 - 31st Street Landfill  
Crest of landfill. Looking south.



— Photo 7 - 31st Street landfill ORIGINAL —  
 — Riverside of landfill, viewed from crest. —  
 — Looking east. Note hay bales/ —



— Photo 8 - 31st Street Landfill. —  
 — Monitoring wells, looking south. —

BASF Wyandotte

R2 P4

F3-8412-17

Photo 5

WV-181

7  
RLO  
2-5-85

31st Street Landfill

River side of landfill, viewed from crest.  
Looking east. Note hay bales

2-4-85

Randall Dickinson

Randall Dickinson

Photo 5 - 31st Street Landfill  
River side of landfill, viewed from crest.  
Looking east. Note hay bales

BASF Wyandotte

R2 P6

F3-8412-17

Photo 4

WV-181

8  
RLO  
2-5-85

31st Street Landfill

Monitoring wells. Looking south

2-4-85

Randall Dickinson

Randall Dickinson

Photo 4 - 31st Street Landfill  
Monitoring wells. Looking south





— Photo 9 - 31st Street Landfill ORIGINAL —  
 — River side of landfill, looking south. —  
 —



— Photo 10 - 31st Street Landfill —  
 — Seepage out onto Guyandotte River, —  
 — looking east. —

BASF Wyandotte  
F3-8412-17  
WV-121

R2P7  
Photo 8  
9  
R&D  
2-5-85

31<sup>st</sup> Street Landfill

River side of landfill. Looking south

2-4-85

Randall Dickinson

Randall Dickinson

Photo 8 - 31st Street Landfill  
River side of landfill. Looking south.

BASF Wyandotte  
F3-8412-17  
WV-121

R2P10  
Photo 6  
10  
R&D  
2-5-85

31<sup>st</sup> Street Landfill

Seepage out onto Guyandotte River. Looking east

2-4-85

Randall Dickinson

Randall Dickinson

Photo 10 - 31st Street Landfill  
Seepage out onto Guyandotte River.  
Looking east.